

Well Name : Squires #2

API # : 067-08335



Photo 1: Wellhead sign.



Photo 2: Location overview.

Well Name : Squires #2

API # : 067-08335



Photo 3: Pipe, regulators, and fittings just off the NE corner of location previous inspection.



Photo 4: Equipment removed.

Well Name : Squires #2

API # : 067-08335



Photo 5: Stained soil at the muffler, ground behind lube oil tank, and supply gas knock out for the Squires 3 previous inspection



Photo 6: Cleaned up impacted soil and gravel.

Well Name : Squires #2

API # : 067-08335



Photo 7: Impacted soil at back of pump jack previous inspection.



Photo 8: Cleaned up impacted soil and gravel.

Well Name : Squires #2

API # : 067-08335



Photo 9: Lube oil tank with no spill prevention previous inspection.



Photo 10: Lube oil tank removed.