

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/28/2018

Submitted Date:

02/28/2018

Document Number:

679904068**FIELD INSPECTION FORM**Loc ID 304377 Inspector Name: Welsh, Brian On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 10112Name of Operator: FOUNDATION ENERGY MANAGEMENT LLCAddress: 5057 KELLER SPRINGS RD STE 650City: ADDISON State: TX Zip: 75001**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**9 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

| Contact Name   | Phone                | Email                           | Comment |
|----------------|----------------------|---------------------------------|---------|
| Grant, Rachael | 918-585-1650 ext 212 | regulatory@foundationenergy.com |         |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name    | Insp Status |
|-------------|------|--------|-------------|------------|-----------|------------------|-------------|
| 261007      | WELL | PR     | 07/30/2001  | GW         | 125-08329 | HELLING 32B-7443 | PR          |

**General Comment:**[Routine Inspection](#)

**Location**

|                    |                           |       |  |
|--------------------|---------------------------|-------|--|
| <b>Lease Road:</b> |                           |       |  |
| Type               | Access                    |       |  |
| comment:           | Trail through farm ground |       |  |
| Corrective Action: |                           | Date: |  |

Overall Good: ☒

|                      |                             |       |  |
|----------------------|-----------------------------|-------|--|
| <b>Signs/Marker:</b> |                             |       |  |
| Type                 | WELLHEAD                    |       |  |
| Comment:             | Lease sign mounted to fence |       |  |
| Corrective Action:   |                             | Date: |  |

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒

|                |      |        |  |  |  |
|----------------|------|--------|--|--|--|
| <b>Spills:</b> |      |        |  |  |  |
| Type           | Area | Volume |  |  |  |

In Containment: No

Comment:

☐ Multiple Spills and Releases?

|                    |                                       |       |  |
|--------------------|---------------------------------------|-------|--|
| <b>Fencing/:</b>   |                                       |       |  |
| Type               | PUMP JACK                             |       |  |
| Comment:           | Metal panels around unit and wellhead |       |  |
| Corrective Action: |                                       | Date: |  |

|                           |                |       |                 |
|---------------------------|----------------|-------|-----------------|
| <b>Equipment:</b>         |                |       | corrective date |
| Type: Prime Mover         | # 1            |       |                 |
| Comment:                  | Electric motor |       |                 |
| Corrective Action:        |                | Date: |                 |
| Type: Ancillary equipment | # 1            |       |                 |
| Comment:                  | Electric panel |       |                 |
| Corrective Action:        |                | Date: |                 |
| Type: Pump Jack           | # 1            |       |                 |
| Comment:                  | Jensen unit    |       |                 |
| Corrective Action:        |                | Date: |                 |

**Venting:**

|                    |    |       |  |
|--------------------|----|-------|--|
| Yes/No             | NO |       |  |
| Comment:           |    |       |  |
| Corrective Action: |    | Date: |  |

**Flaring:**

|      |  |  |
|------|--|--|
| Type |  |  |
|------|--|--|

|                    |  |       |  |
|--------------------|--|-------|--|
| Comment:           |  |       |  |
| Corrective Action: |  | Date: |  |

| Inspected Facilities |   |       |      |             |           |         |    |               |    |
|----------------------|---|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID:         | 261007  | Type: | WELL | API Number: | 125-08329 | Status: | PR | Insp. Status: | PR |
| Producing Well       |   |       |      |             |           |         |    |               |    |
| Comment:             | Producing. Casing production. Central meter run for (Helling 43-7 & Helling 32-7443) 1450' SE @ 39.72259/-102.21825 |       |      |             |           |         |    |               |    |
| Corrective Action:   |   |       |      |             |           |         |    | Date:         |    |

Reclamation - Storm Water - Pit

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Other            | Pass            |                         |                       |               |                          |         |

Comment: Location is farmed over

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT