

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/23/2018

Submitted Date:

02/23/2018

Document Number:

689701086**FIELD INSPECTION FORM**Loc ID 334129 Inspector Name: LONGWORTH, MIKE On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10456Name of Operator: CAERUS PICEANCE LLCAddress: 1001 17TH STREET #1600City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:9 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

| Contact Name | Phone | Email | Comment |
|-------------------|-------|---------------------------------------|---------------------------|
| , Caerus Piceance | | COGCC.inspections@caerusoilandgas.com | Piceance inspections only |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|-------------------|-------------|
| 278336 | WELL | PR | 10/18/2005 | GW | 045-10866 | CASS-GARBER 1-52 | PR |
| 278493 | WELL | PR | 08/19/2015 | GW | 045-10886 | CASS-GARBER 1-31A | PR |
| 278825 | WELL | PR | 01/05/2011 | GW | 045-10947 | CASS-DUNCAN 1-32A | PR |
| 278826 | WELL | SI | 10/01/2017 | GW | 045-10946 | CASS-DUNCAN 1-32B | PR |
| 278828 | WELL | SI | 10/01/2017 | GW | 045-10944 | CASS-GARBER 1-31B | PR |
| 278829 | WELL | SI | 11/01/2017 | GW | 045-10943 | CASS-GARBER 1-31C | PR |
| 278830 | WELL | PR | 08/31/2007 | GW | 045-10942 | CASS-NOCKS 1-41 | PR |

General Comment:

Location

| | | | |
|--------------------|--------|-------|--|
| Lease Road: | | | |
| Type | Access | | |
| comment: | | | |
| Corrective Action | L | Date: | |

Overall Good: ☒

| | | | |
|----------------------|----------------------|-------|--|
| Signs/Marker: | | | |
| Type | WELLHEAD | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | TANK LABELS/PLACARDS | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | BATTERY | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Emergency Contact Number:

Comment: 866-580-9382

Corrective Action:

Date: _____

Good Housekeeping:

| | | | |
|--------------------|-------|-------|--|
| Type | TRASH | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Overall Good: ☒

| | | | | |
|----------------|------|--------|--|--|
| Spills: | | | | |
| Type | Area | Volume | | |

In Containment: No

Comment:

☐ Multiple Spills and Releases?

| | | | |
|--------------------|--------------|-------|--|
| Fencing/: | | | |
| Type | WELLHEAD | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | TANK BATTERY | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | SEPARATOR | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

| | | | |
|-----------------------------------|-----|--|-----------------|
| Equipment: | | | corrective date |
| Type: Bird Protectors | # 5 | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Type: Plunger Lift | # 7 | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Type: Horizontal Heated Separator | # 7 | | |
| Comment: | | | |
| Corrective Action: | | | Date: |

Tanks and Berms:

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|--------------------|---|----------|-----------|---------|--------|
| CONDENSATE | 1 | 300 BBLS | STEEL AST | | , |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

Paint

| | | |
|------------------|----------|--|
| Condition | Adequate | |
| Other (Content) | | |
| Other (Capacity) | | |
| Other (Type) | | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
| Earth | Adequate | Walls Sufficent | Base Sufficent | Adequate |
| Comment: | | | | |
| Corrective Action: | | | | Date: |

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|--------------------|---|----------|-----------|---------|--------|
| CONDENSATE | 2 | 300 BBLS | STEEL AST | | , |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

Paint

| | | |
|------------------|----------|--|
| Condition | Adequate | |
| Other (Content) | | |
| Other (Capacity) | | |
| Other (Type) | | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
| Metal | Adequate | Walls Sufficent | Base Sufficent | Adequate |
| Comment: | | | | |
| Corrective Action: | | | | Date: |

Venting:

| | | | |
|--------------------|----|-------|--|
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Flaring:

| | | |
|--------------------|--|-------|
| Type | | |
| Comment: | | |
| Corrective Action: | | Date: |

| |
|--|
| |
|--|

Inspected Facilities

| | | | | |
|---------------------|------------|-----------------------|------------|------------------|
| Facility ID: 278336 | Type: WELL | API Number: 045-10866 | Status: PR | Insp. Status: PR |
|---------------------|------------|-----------------------|------------|------------------|

Producing Well

Comment: Producing well

Corrective Action:

Date:

| | | | | |
|---------------------|------------|-----------------------|------------|------------------|
| Facility ID: 278493 | Type: WELL | API Number: 045-10886 | Status: PR | Insp. Status: PR |
|---------------------|------------|-----------------------|------------|------------------|

Producing Well

Comment: Producing well

Corrective Action:

Date:

| | | | | |
|---------------------|------------|-----------------------|------------|------------------|
| Facility ID: 278825 | Type: WELL | API Number: 045-10947 | Status: PR | Insp. Status: PR |
|---------------------|------------|-----------------------|------------|------------------|

Producing Well

Comment: Producing well

Corrective Action:

Date:

| | | | | |
|---------------------|------------|-----------------------|------------|------------------|
| Facility ID: 278826 | Type: WELL | API Number: 045-10946 | Status: SI | Insp. Status: PR |
|---------------------|------------|-----------------------|------------|------------------|

Producing Well

Comment: Producing well

Corrective Action:

Date:

| | | | | |
|---------------------|------------|-----------------------|------------|------------------|
| Facility ID: 278828 | Type: WELL | API Number: 045-10944 | Status: SI | Insp. Status: PR |
|---------------------|------------|-----------------------|------------|------------------|

Producing Well

Comment: Producing well

Corrective Action:

Date:

| | | | | |
|---------------------|------------|-----------------------|------------|------------------|
| Facility ID: 278829 | Type: WELL | API Number: 045-10943 | Status: SI | Insp. Status: PR |
|---------------------|------------|-----------------------|------------|------------------|

Producing Well

Comment: Producing well

Corrective Action:

Date:

| | | | | |
|---------------------|------------|-----------------------|------------|------------------|
| Facility ID: 278830 | Type: WELL | API Number: 045-10942 | Status: PR | Insp. Status: PR |
|---------------------|------------|-----------------------|------------|------------------|

Producing Well

Comment: Producing well

Corrective Action:

Date:

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------------------------|---|
| 401554386 | INSPECTION SUBMITTED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4386032 |
| 689701087 | Inspection 689701086 photo | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4386016 |