

Inspection Photos
Location Name: A 14 OU
Location ID: 334067



Photo 1. Wellheads.



Photo 2. Damaged tank containment.

Inspection Photos
Location Name: A 14 OU
Location ID: 334067



Photo 3. Damaged tank containment.



Photo 4. Damaged tank containment.