

Inspection Photos
Location Name: Stromberger 22-E Pad
Location ID: 444315
Inspection Date: 3/2/2018



Photo 1 – Sample Location #1



Photo 2 - Overview of Sample Location #1 and ignition area of fire.



Inspection Photos
Location Name: Stromberger 22-E Pad
Location ID: 444315
Inspection Date: 3/2/2018



Photo 3 - Sample Location #2



Photo 4 – Overview of Sample Location #2 and ignition area of fire.



Inspection Photos
Location Name: Stromberger 22-E Pad
Location ID: 444315
Inspection Date: 3/2/2018



Photo 5 – Sample Location 3



Photo 6 – Overview of sample location 3