

# *Inspection Photos*

*Loc#440634*

*Operator: URSA*

*Inspection Number: 680102727*

*Inspection Date: 2/27/2018*





Photo#1:  
Overview of Location to North

February 27, 2018



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Ursa B&V Loc#440634



Photo#2: Area of Missing BMP  
View to NE



Photo#3: Area of Missing BMP  
View to SE

February 27, 2018




Photo#4:  
Subsidence commencing in area of missing BMP; adjacent to electrical Box (?).

February 27, 2018



Photo#5:  
Wattles installed along West Track.

February 27, 2018



Photo#6:  
Retention area at Southeast Corner



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Ursa B&V Loc#440634