

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/28/2018

Submitted Date:

03/02/2018

Document Number:

682600457**FIELD INSPECTION FORM**
 Loc ID 439367 Inspector Name: Kosola, Jason On-Site Inspection ☐ 2A Doc Num:                     
**Operator Information:**OGCC Operator Number: 10412Name of Operator: AUSCO PETROLEUM INCAddress: 113 N SANTA FE AVENUECity: FLORENCE State: CO Zip: 81226**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**2 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Goudy, Guy		ggoudy@fremontpetroleum.com	
Hart, Tim		thart@fremontpetroleum.com	
Axelson, John		john.axelson@state.co.us	
Goss, Aaron	303-495-0327	agoss@fremontpetroleum.com	All Inspections
Ferrin, Jeremy		jeremy.ferrin@state.co.us	

**General Comment:**

This is an environmental inspection. Any corrective actions from previous inspections that have not been addressed are still applicable.

ALLEGED VIOLATION – Operator was granted a one-time only, extension of the use of the Magellan Drilling Pit. The Drilling Pit is to be closed no later than November 15, 2017. Pit remains open as of inspection on 2/28/2018. COGCC Remediation #10865 was approved for pit closure on 1/10/2018. The COGCC has not received any further documentation of pit closure and the pit remains open 105 days past the closure date (see attached photos).

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
682600458	Inspection photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4392550">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4392550</a>