



Photo#1:
Overview of Location to Northeast.
February 27, 2018



Photo#2:

Vegetation in Interim Reclamation areas appears well established. View along Cut Slope
February 27, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Caerus M. Dutton Loc#334367



Photo#2:
View along Fill slope Berm.
February 27, 2018