

# Inspection Photos

API: 05-067-08216

Operator: BP AMERICA PRODUCTION COMPANY

Inspection Number: 680602504

Inspection Date: 2/26/2018



**Photo 1. View of the project area from the southeastern corner facing center.**



**Photo 2. View of the northern portion of the project area from the northeastern corner facing westward. Revegetation is progressing with grasses such as western wheatgrass (*Pascopyrum smithii*) and intermediate wheatgrass (*Thinopyron intermedium*).**



**Photo 3. View of the southern portion of the project area from the southwestern corner facing eastward. Poor revegetation on berms and fill slopes. These should be seeded in spring 2018.**



**Photo 4. View of stormwater controls in the eastern portion of the project area facing northward. Appear to be functioning at this time .**



**Photo 5. View of silt trap in the northwestern portion of the project area, appears to functioning at this time.**