



**Location**

Overall Good:

**Signs/Marker:**

Type	DRILLING/RECOMP		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	<input type="text"/>	Date:	
Corrective Action:	<input type="text"/>		

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type	LOCATION		
Comment:	Approx 43' sound walls on West and South end of location		
Corrective Action:		Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type	Field Flare		
Comment:	Not in use at time of the inspection		
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 453223 Type: WELL API Number: 123-45983 Status: XX Insp. Status: DG

Facility ID: 453224 Type: WELL API Number: 123-45984 Status: XX Insp. Status: DG

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Ditches	Pass	Ditches	Pass	Vehicle Tracking	Pass	
Compaction	Pass	Compaction	Pass	Covering Materials	Pass	
Waddles	Pass	Culverts	Pass			
Gravel	Pass	Gravel	Pass	Material Handling And Spill Prevention	Pass	

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT