

Inspection Photos
Location Name: Burnett #2-1
API: 05-067-07769



Burnett #2-1 location photo.



Burnett #2-1 pump jack and well head.

Inspection Photos
Location Name: Burnett #2-1
API: 05-067-07769



Well head is stained with white residue.



PBV with drip pot on load out line.

Inspection Photos
Location Name: Burnett #2-1
API: 05-067-07769



Wattles in erosion channel on western edge of location.



Erosional feature along western edge of location.