

Location Name: Keely B11-63-1HN

Location: 429244, Spill ID: 454197

Inspection Date: 3/6/2018



Photo of active excavation area. Middle steel line is subject produced water liner for the Keely B11-63-1HN. Release occurred at collar on far end of line in photo.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources