

Inspection Photos

02/26/2018

Operator: BRITISH AMERICAN OIL PROD CO -
10558

Location ID: 388949

Inspection Doc. Number: 682503191

Logan County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC

Inspection Photos
Operator: BRITISH AMERICAN OIL PROD CO - 10558
Location ID: 388949



Photo 1: Photo taken from the location, facing north. Photo shows the vegetation over the reclamation area.



Photo 2: Photo taken from the location, facing east. Photo shows the vegetation over the reclamation area.

Inspection Photos
Operator: BRITISH AMERICAN OIL PROD CO - 10558
Location ID: 388949



Photo 3: Photo taken from the location, facing south. Photo shows the vegetation over the reclamation area.



Photo 4: Photo taken from the location, facing west. Photo shows the vegetation over the reclamation area.