

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/28/2018

Submitted Date:

03/02/2018

Document Number:

682600457

FIELD INSPECTION FORM

Loc ID 439367 Inspector Name: Kosola, Jason On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10412
Name of Operator: AUSCO PETROLEUM INC
Address: 113 N SANTA FE AVENUE
City: FLORENCE State: CO Zip: 81226

Findings:

- 2 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Goudy, Guy		ggoudy@fremontpetroleum.com	
Axelson, John		john.axelson@state.co.us	
Goss, Aaron	303-495-0327	agoss@fremontpetroleum.com	All Inspections
Ferrin, Jeremy		jeremy.ferrin@state.co.us	
Hart, Tim		thart@fremontpetroleum.com	

General Comment:

This is an environmental inspection. Any corrective actions from previous inspections that have not been addressed are still applicable.

ALLEGED VIOLATION – Operator was granted a one-time only, extension of the use of the Magellan Drilling Pit. The Drilling Pit is to be closed no later than November 15, 2017. Pit remains open as of inspection on 2/28/2018. COGCC Remediation #10865 was approved for pit closure on 1/10/2018. The COGCC has not received any further documentation of pit closure and the pit remains open 105 days past the closure date (see attached photos).

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401562131	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4392554
682600458	Inspection photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4392550