

Inspection Photos

Loc#419862

Operator: Terra

Inspection Number: 680102743

Inspection Date: 2/27/2018



Photo#1:

Overview of Location to North ; arrow indicates area where BMP maintenance / installation is needed.

February 27, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Ursa B&V Loc#440634



Photo#2:

View down Cut Slope Drain to West; arrow indicates area where BMP maintenance / installation is needed.

February 27, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Ursa B&V Loc#440634



Photo#3:

Area at base of armored drain where Stormwater that has undercut further up slope exits and has deposited considerable Sediment.

February 27, 2018



Photo#4: