

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/05/2018

Submitted Date:

03/05/2018

Document Number:

689401010

FIELD INSPECTION FORM

Loc ID 334546 Inspector Name: CONKLIN, CURTIS On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10433
Name of Operator: LARAMIE ENERGY LLC
Address: 1401 SEVENTEENTH STREET #1400
City: DENVER State: CO Zip: 80202

Findings:

- 3 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

Contact Information:

| Contact Name | Phone | Email | Comment |
|--------------------|-------|---------------------------------------|---------------------------------|
| Laramie Energy LLC | | cogccnotifications@laramie-energy.com | All Inspections |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|-----------------------|-------------|
| 453275 | WELL | DG | 03/04/2018 | | 077-10541 | Gunderson 0994-13-06W | DG |

General Comment:

[This is a routine drilling inspection, any corrective actions not addressed from previous inspections are still applicable.](#)

Location

Overall Good:

Signs/Marker:

| | | | |
|--------------------|-----------------|-------|--|
| Type | DRILLING/RECOMP | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Emergency Contact Number:

Comment:

Corrective Action: Date: _____

Overall Good:

Spills:

| Type | Area | Volume | | |
|------|------|--------|--|--|
| | | | | |

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

| | | | |
|--------------------|----|-------|--|
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Flaring:

| | | |
|--------------------|--|-------|
| Type | | |
| Comment: | | |
| Corrective Action: | | Date: |

Inspected Facilities

Facility ID: 453275 Type: WELL API Number: 077-10541 Status: DG Insp. Status: DG

Well Drilling

Rig: Rig Name: H&P 522 Pusher/Rig Manager: Tyler Hale
 Permit Posted: Yes Access Sign: Yes

Well Control Equipment:

Pipe Ram: YES Blind Ram: YES Hydril Type: YES
 Pressure Test BOP: Pass Test Pressure PSI: _____ Safety Plan: YES

Drill Fluids

Management:

Lined Pit: _____ Unlined Pit: _____ Closed Loop: _____ Semi-Closed Loop: _____
 Multi-Well: YES Disposal Location: On location

Comment: Spud 3/3/18. Surface TD @ 1,555. BOP test on 3/4/18. Notifications have been recieved.

Corrective Action: _____ Date: _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-----------------------|---|
| 401563326 | INSPECTION SUBMITTED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4393617 |
| 689401011 | Gunderson 0994-13-06W | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4393614 |