

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/13/2018

Submitted Date:

03/13/2018

Document Number:

679904126**FIELD INSPECTION FORM**

Loc ID 304434 Inspector Name: Welsh, Brian On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 10112Name of Operator: FOUNDATION ENERGY MANAGEMENT LLCAddress: 5057 KELLER SPRINGS RD STE 650City: ADDISON State: TX Zip: 75001**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:11 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

| Contact Name | Phone | Email | Comment |
|----------------|----------------------|---------------------------------|---------|
| Grant, Rachael | 918-585-1650 ext 212 | regulatory@foundationenergy.com | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 261479 | WELL | PR | 12/28/2001 | GW | 125-08410 | CURE 44-28443 | PR |

General Comment:[Routine Inspection](#)

Location

| | | | |
|--------------------|---------------------------|-------|--|
| Lease Road: | | | |
| Type | Access | | |
| comment: | Trail through farm ground | | |
| Corrective Action | | Date: | |

Overall Good: ☒

| | | | |
|----------------------|-----------------------------|-------|--|
| Signs/Marker: | | | |
| Type | WELLHEAD | | |
| Comment: | Lease sign mounted to fence | | |
| Corrective Action: | | Date: | |
| Type | TANK LABELS/PLACARDS | | |
| Comment: | Metal sign by water tank | | |
| Corrective Action: | | Date: | |

Emergency Contact Number:

| | | |
|--------------------|--|-------------|
| Comment: | | Date: _____ |
| Corrective Action: | | |

Overall Good: ☒

| | | | | |
|----------------|------|--------|--|--|
| Spills: | | | | |
| Type | Area | Volume | | |

In Containment: No

Comment: ☐ Multiple Spills and Releases?

| | | | |
|--------------------|---------------------------------------|-------|--|
| Fencing/: | | | |
| Type | PUMP JACK | | |
| Comment: | Metal panels around unit and wellhead | | |
| Corrective Action: | | Date: | |

| | | | |
|---------------------------|----------------|-------|-----------------|
| Equipment: | | | corrective date |
| Type: Pump Jack | # 1 | | |
| Comment: | Jensen unit | | |
| Corrective Action: | | Date: | |
| Type: Prime Mover | # 1 | | |
| Comment: | Electric motor | | |
| Corrective Action: | | Date: | |
| Type: Ancillary equipment | # 1 | | |
| Comment: | Electric panel | | |
| Corrective Action: | | Date: | |

Tanks and Berms:

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|----------------|---|----------|----------------|---------|-----------------------|
| PRODUCED WATER | 1 | OTHER | PBV FIBERGLASS | | 39.677640,-102.178120 |

| | | | |
|--------------------|----------------------------------|-------|--|
| Comment: | Fiberglass water tank 50% buried | | |
| Corrective Action: | | Date: | |

Paint

| | | |
|------------------|---------|--|
| Condition | | |
| Other (Content) | | |
| Other (Capacity) | 210bbbs | |
| Other (Type) | | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
| | | | | |
| Comment: | | | | |
| Corrective Action: | | | | Date: |

Venting:

| | | | |
|--------------------|----|-------|--|
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Flaring:

| | | |
|--------------------|--|-------|
| Type | | |
| Comment: | | |
| Corrective Action: | | Date: |

| Inspected Facilities | | | | | | | | | |
|----------------------|--|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID: | 261479 | Type: | WELL | API Number: | 125-08410 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing. Casing production. Central meter run for (Cure 33B-28443, 44-28443) 1900' W @ 39.67734/-102.18729 | | | | | | | | |
| Corrective Action: | | | | | | | | Date: | |

Reclamation - Storm Water - Pit

Storm Water:

| | | | | | | |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
| Other | Pass | Other | Pass | | | |

Comment: Location and access are farmed over

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT