



## Form Information

Form Name:	<b>Compliance Follow Up Form</b>
Submitter Name:	Clay Elkins (celkins@gobrainstorm.net)
Submission Date:	Feb 13, 2018 7:16:18 AM MST
Server Receive Date:	Feb 27, 2018 7:33:07 AM MST
Reference Number:	20180213-1873074667
Location:	3601 N 1st St, Bloomfield, NM 87413, United States Feb 13, 2018 7:16:16 AM MST [ <a href="#">View Map</a> ]

## Information

Name	celkins@gobrainstorm.net
Date	Feb 7, 2018
Well Name	ELDRIDGE 25-01 1
Select State	Colorado
Work type	COGCC Inspection AR
Action Complete	Compliance Inspection Actions Grading/recontour Erosion Repairs Install Rock Run Down Repaired Berm

Picture North to South



Picture South to North



Picture East to West



Picture West to East



Additional photos



Additional photos

