

Form Information

---

Form Name:	<b>Compliance Follow Up Form</b>
Submitter Name:	Clay Elkins (celkins@gobrainstorm.net)
Submission Date:	Mar 12, 2018 7:13:18 AM MDT
Server Receive Date:	Mar 12, 2018 7:13:31 AM MDT
Reference Number:	20180312-1874583178
Location:	3601 N 1st St, Bloomfield, NM 87413, United States
	Mar 12, 2018 7:12:26 AM MDT [ <a href="#">View Map</a> ]

Information

---

Name	celkins@gobrainstorm.net
Date	Mar 9, 2018
Well Name	HESTER GAS UNIT 2
Select State	Colorado
Work type	COGCC Inspection AR
Action Complete	Compliance Inspection Actions Erosion Repairs Install Rock Run Down Clean Up Weed Debris Replaced/Repaired Tank Signs Grading of Well Pad

Picture North to South



Picture South to North



Picture East to West



Picture West to East

