



Form Information

| | |
|----------------------|--|
| Form Name: | Compliance Follow Up Form |
| Submitter Name: | Clay Elkins (celkins@gobrainstorm.net) |
| Submission Date: | Mar 12, 2018 7:09:59 AM MDT |
| Server Receive Date: | Mar 12, 2018 8:52:43 AM MDT |
| Reference Number: | 20180312-1874583110 |
| Location: | 3601 N 1st St, Bloomfield, NM 87413, United States |
| | Mar 12, 2018 7:09:21 AM MDT [View Map] |

Information

| | |
|-----------------|---|
| Name | celkins@gobrainstorm.net |
| Date | Mar 9, 2018 |
| Well Name | MCCARVILLE GAS UNIT C 2 |
| Select State | Colorado |
| Work type | COGCC Inspection AR |
| Action Complete | Compliance Inspection Actions Erosion Repairs Install Rock Run Down Clean up Operator Debris Clean Up Contaminated Soils Grading of Well Pad |

Picture North to South



Picture South to North



Picture East to West



Picture West to East



Additional photos

