

BP L48 San Juan




Form Information

Form Name:	Compliance Follow Up Form
Submitter Name:	Clay Elkins (celkins@gobrainstorm.net)
Submission Date:	Mar 12, 2018 8:59:05 AM MDT
Server Receive Date:	Mar 12, 2018 10:08:09 AM MDT
Reference Number:	20180312-1874593077
Location:	2655 Bloomfield Hwy, Farmington, NM 87401, United States
	Mar 12, 2018 8:57:30 AM MDT [View Map]

Information

Name	celkins@gobrainstorm.net
Date	Mar 9, 2018
Well Name	FEDERAL LAND BANK GAS UNIT G 1
Select State	Colorado
Work type	COGCC Inspection AR
Action Complete	Compliance Inspection Actions Erosion Repairs Install Rock Run Down Clean Up Contaminated Soils Repaired Berm

Picture North to South



Picture South to North



Picture East to West



Picture West to East



Additional photos

