

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/05/2018

Submitted Date:

03/05/2018

Document Number:

689701126**FIELD INSPECTION FORM**Loc ID 334653 Inspector Name: LONGWORTH, MIKE On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 10456Name of Operator: CAERUS PICEANCE LLCAddress: 1001 17TH STREET #1600City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**13 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

| Contact Name      | Phone | Email                                     | Comment                   |
|-------------------|-------|---|---------------------------|
| , Caerus Piceance |       | COGCC.inspections@caerus<br>oilandgas.com | Piceance inspections only |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name           | Insp Status |
|-------------|------|--------|-------------|------------|-----------|-------------------------|-------------|
| 270427      | WELL | PR     | 01/01/2005  | GW         | 045-09558 | CLEM 15-13              | PR          |
| 298053      | WELL | PR     | 07/18/2009  | GW         | 045-17045 | CLEM JR. 15-7BB(PB-15)  | PR          |
| 298056      | WELL | PR     | 07/14/2009  | GW         | 045-17046 | CLEM JR. 15-3(PB-15)    | PR          |
| 298060      | WELL | PR     | 07/05/2009  | GW         | 045-17047 | CLEM JR. 15-6 (PB-15)   | PR          |
| 298061      | WELL | PR     | 07/09/2009  | GW         | 045-17048 | CLEM JR. 15-6BB(PB-15)  | PR          |
| 298062      | WELL | PR     | 07/14/2009  | GW         | 045-17049 | CLEM JR. 15-2BB(PB-15)  | PR          |
| 298393      | WELL | PR     | 08/09/2009  | GW         | 045-17181 | CLEM JR. 15-8 (PB-15)   | PR          |
| 298394      | WELL | PR     | 08/07/2009  | GW         | 045-17180 | CLEM JR. 15-7(PB-15)    | PR          |
| 298395      | WELL | PR     | 08/12/2009  | GW         | 045-17179 | CLEM JR. 15-1BB (PB-15) | PR          |
| 298711      | WELL | PR     | 07/02/2009  | GW         | 045-17378 | CLEM JR. 15-3BB(PB-15)  | PR          |

**General Comment:**

**Location**Overall Good: ☒

|                      |   |       |  |
|----------------------|---|-------|--|
| <b>Signs/Marker:</b> |   |       |  |
| Type                 | OTHER   |       |  |
| Comment:             | Airs Id. has incorrect county code on tanks. See photo. |       |  |
| Corrective Action:   |   | Date: |  |
| Type                 | TANK LABELS/PLACARDS                                    |       |  |
| Comment:             |   |       |  |
| Corrective Action:   |   | Date: |  |
| Type                 | BATTERY   |       |  |
| Comment:             |   |       |  |
| Corrective Action:   |   | Date: |  |
| Type                 | WELLHEAD  |       |  |
| Comment:             |   |       |  |
| Corrective Action:   |   | Date: |  |

Emergency Contact Number:

Comment: 970-285-2615

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒

|                |      |        |  |
|----------------|------|--------|--|
| <b>Spills:</b> |      |        |  |
| Type           | Area | Volume |  |

In Containment: No

Comment:

☐ Multiple Spills and Releases?

|                                   |      |       |                 |
|-----------------------------------|------|-------|-----------------|
| <b>Equipment:</b>                 |      |       | corrective date |
| Type: Plunger Lift                | # 10 |       |                 |
| Comment:                          |      |       |                 |
| Corrective Action:                |      | Date: |                 |
| Type: Horizontal Heated Separator | # 10 |       |                 |
| Comment:                          |      |       |                 |
| Corrective Action:                |      | Date: |                 |
| Type: Bird Protectors             | # 6  |       |                 |
| Comment:                          |      |       |                 |
| Corrective Action:                |      | Date: |                 |

**Tanks and Berms:**

|                    |   |          |           |         |        |
|--------------------|---|----------|-----------|---------|--------|
| Contents           | # | Capacity | Type      | Tank ID | SE GPS |
| CONDENSATE         | 4 | 300 BBLS | STEEL AST |         | ,      |
| Comment:           |   |          |           |         |        |
| Corrective Action: |   |          |           |         | Date:  |

**Paint**

|                  |          |  |
|------------------|----------|--|
| Condition        | Adequate |  |
| Other (Content)  |          |  |
| Other (Capacity) |          |  |
| Other (Type)     |          |  |

**Berms**

|                    |          |                     |                     |             |       |
|--------------------|----------|---------------------|---------------------|-------------|-------|
| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |       |
| Metal              | Adequate | Walls Sufficent     | Base Sufficent      | Adequate    |       |
| Comment:           |          |                     |                     |             |       |
| Corrective Action: |          |                     |                     |             | Date: |

**Venting:**

|                    |    |       |  |
|--------------------|----|-------|--|
| Yes/No             | NO |       |  |
| Comment:           |    |       |  |
| Corrective Action: |    | Date: |  |

**Flaring:**

|                    |  |       |
|--------------------|--|-------|
| Type               |  |       |
| Comment:           |  |       |
| Corrective Action: |  | Date: |

| Inspected Facilities  |                |       |      |             |           |         |    |               |    |
|-----------------------|----------------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID:          | 270427         | Type: | WELL | API Number: | 045-09558 | Status: | PR | Insp. Status: | PR |
| <b>Producing Well</b> |                |       |      |             |           |         |    |               |    |
| Comment:              | Producing well |       |      |             |           |         |    |               |    |
| Corrective Action:    |                |       |      |             |           | Date:   |    |               |    |
| Facility ID:          | 298053         | Type: | WELL | API Number: | 045-17045 | Status: | PR | Insp. Status: | PR |
| <b>Producing Well</b> |                |       |      |             |           |         |    |               |    |
| Comment:              | Producing well |       |      |             |           |         |    |               |    |
| Corrective Action:    |                |       |      |             |           | Date:   |    |               |    |
| Facility ID:          | 298056         | Type: | WELL | API Number: | 045-17046 | Status: | PR | Insp. Status: | PR |
| <b>Producing Well</b> |                |       |      |             |           |         |    |               |    |
| Comment:              | Producing well |       |      |             |           |         |    |               |    |
| Corrective Action:    |                |       |      |             |           | Date:   |    |               |    |
| Facility ID:          | 298060         | Type: | WELL | API Number: | 045-17047 | Status: | PR | Insp. Status: | PR |
| <b>Producing Well</b> |                |       |      |             |           |         |    |               |    |
| Comment:              | Producing well |       |      |             |           |         |    |               |    |
| Corrective Action:    |                |       |      |             |           | Date:   |    |               |    |
| Facility ID:          | 298061         | Type: | WELL | API Number: | 045-17048 | Status: | PR | Insp. Status: | PR |
| <b>Producing Well</b> |                |       |      |             |           |         |    |               |    |
| Comment:              | Producing well |       |      |             |           |         |    |               |    |
| Corrective Action:    |                |       |      |             |           | Date:   |    |               |    |
| Facility ID:          | 298062         | Type: | WELL | API Number: | 045-17049 | Status: | PR | Insp. Status: | PR |
| <b>Producing Well</b> |                |       |      |             |           |         |    |               |    |
| Comment:              | Producing well |       |      |             |           |         |    |               |    |
| Corrective Action:    |                |       |      |             |           | Date:   |    |               |    |
| Facility ID:          | 298393         | Type: | WELL | API Number: | 045-17181 | Status: | PR | Insp. Status: | PR |
| <b>Producing Well</b> |                |       |      |             |           |         |    |               |    |
| Comment:              | Producing well |       |      |             |           |         |    |               |    |
| Corrective Action:    |                |       |      |             |           | Date:   |    |               |    |
| Facility ID:          | 298394         | Type: | WELL | API Number: | 045-17180 | Status: | PR | Insp. Status: | PR |
| <b>Producing Well</b> |                |       |      |             |           |         |    |               |    |
| Comment:              | Producing well |       |      |             |           |         |    |               |    |
| Corrective Action:    |                |       |      |             |           | Date:   |    |               |    |

|              |        |       |      |             |           |         |    |               |    |
|--------------|--------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID: | 298395 | Type: | WELL | API Number: | 045-17179 | Status: | PR | Insp. Status: | PR |
|--------------|--------|-------|------|-------------|-----------|---------|----|---------------|----|

**Producing Well**Comment: [Producing well](#)

Corrective Action:

Date:

|              |        |       |      |             |           |         |    |               |    |
|--------------|--------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID: | 298711 | Type: | WELL | API Number: | 045-17378 | Status: | PR | Insp. Status: | PR |
|--------------|--------|-------|------|-------------|-----------|---------|----|---------------|----|

**Producing Well**Comment: [Producing well](#)

Corrective Action:

Date:

**Reclamation - Storm Water - Pit****Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
|                  |                 | Gravel                  | Pass                  |               |                          |         |
| Compaction       | Pass            |                         |                       |               |                          |         |
| Gravel           | Pass            |                         |                       |               |                          |         |
| Berms            | Pass            |                         |                       |               |                          |         |
|                  |                 | Compaction              | Pass                  |               |                          |         |
|                  |                 | Ditches                 | Pass                  |               |                          |         |

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description                 | URL   |
|--------------|-----------------------------|---|
| 401567935    | INSPECTION SUBMITTED        | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4397459">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4397459</a> |
| 689701127    | Inspection 689701126 photos | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4397452">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4397452</a> |