

Inspection Photos
Location Name: Dwinell 2
API: 05-057-05127



Photo 1. Overview of location taken at entrance facing southeast.

Inspection Photos
Location Name: Dwinell 2
API: 05-057-05127



Photo 2. Wellhead with unmarked 1" steel riser.



Photo 3. Wellhead sign knocked over.