

Inspection Photos  
Location Name: Dwinell 1  
API: 05-057-05129



**Photo 1. Overview of location taken at entrance facing southeast.**

Inspection Photos  
Location Name: Dwinell  
API: 05-057-05129



**Photo 2. Wellhead.**



**Photo 3. Landfarm 1 of 2. 40.82212, -106.23297**

Inspection Photos  
Location Name: Dwinell  
API: 05-057-05129



**Photo 4. Landfarm 2 of 2. 40.82214, -106.23263.**



**Photo 5. Equipment stored on location.**

Inspection Photos  
Location Name: Dwinell  
API: 05-057-05129



**Photo 6. Equipment stored on location.**



**Photo 7. Pit with sagging netting. Unmarked 2" steel riser entering pit from right. 40.82189, -106.23278**