

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/15/2018

Submitted Date:

03/15/2018

Document Number:

689401040

**FIELD INSPECTION FORM**

Loc ID 334499 Inspector Name: CONKLIN, CURTIS On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

THIS IS A FOLLOW UP INSPECTION

FOLLOW UP INSPECTION REQUIRED

NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

12 Number of Comments

0 Number of Corrective Actions

Corrective Action Response Requested

**Operator Information:**

OGCC Operator Number: 10433

Name of Operator: LARAMIE ENERGY LLC

Address: 1401 SEVENTEENTH STREET #1400

City: DENVER State: CO Zip: 80202

**Contact Information:**

| Contact Name       | Phone | Email                                 | Comment                         |
|--------------------|-------|---------------------------------------|---------------------------------|
| Laramie Energy LLC |       | cogccnotifications@laramie-energy.com | <a href="#">All Inspections</a> |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name        | Insp Status |
|-------------|------|--------|-------------|------------|-----------|----------------------|-------------|
| 287345      | WELL | PR     | 12/01/2017  | GW         | 077-09167 | WOODS-SPANGLER 15-11 | PR          |
| 287346      | WELL | PR     | 06/24/2008  | GW         | 077-09166 | WOODS-SPANGLER 15-12 | PR          |
| 287347      | WELL | PR     | 12/01/2017  | GW         | 077-09165 | WOODS-SPANGLER 15-13 | PR          |
| 287348      | WELL | PR     | 12/11/2007  | GW         | 077-09164 | WOODS-SPANGLER 15-14 | PR          |
| 287349      | WELL | PR     | 04/26/2007  | GW         | 077-09163 | WOODS-SPANGLER 21-1  | PR          |
| 287350      | WELL | PR     | 10/20/2010  | GW         | 077-09162 | WOODS-SPANGLER 22-4  | PR          |
| 288356      | WELL | PR     | 12/29/2007  | GW         | 077-09214 | WOODS-SPANGLER 16-16 | PR          |

**General Comment:**

[This is a routine field inspection, any corrective actions not addressed from previous inspections are still applicable.](#)

**Location**

Overall Good:

**Signs/Marker:**

|                    |                      |       |  |
|--------------------|----------------------|-------|--|
| Type               | WELLHEAD             |       |  |
| Comment:           |                      |       |  |
| Corrective Action: |                      | Date: |  |
| Type               | TANK LABELS/PLACARDS |       |  |
| Comment:           |                      |       |  |
| Corrective Action: |                      | Date: |  |

Emergency Contact Number:

Comment: [Posted Emergency Contact Number 1-970-248-0497](#)

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Good Housekeeping:**

|                    |   |       |  |
|--------------------|---|-------|--|
| Type               | STORAGE OF SUPL   |       |  |
| Comment:           | Equipment for winter road maintenance and trailers stored on location at time of inspection. Equipment not needed for the production of lease should not be stored on location to comply with Rule 603.f. |       |  |
| Corrective Action: |   | Date: |  |

Overall Good:

**Spills:**

| Type | Area | Volume |  |  |
|------|------|--------|--|--|
|      |      |        |  |  |

In Containment: No

Comment: \_\_\_\_\_

Multiple Spills and Releases?

**Fencing/:**

|                    |              |       |  |
|--------------------|--------------|-------|--|
| Type               | TANK BATTERY |       |  |
| Comment:           |              |       |  |
| Corrective Action: |              | Date: |  |
| Type               | WELLHEAD     |       |  |
| Comment:           |              |       |  |
| Corrective Action: |              | Date: |  |

**Tanks and Berms:**

| Contents           | #     | Capacity | Type | Tank ID | SE GPS      |
|--------------------|-------|----------|------|---------|-------------|
|                    |       |          |      |         |             |
| Comment:           | _____ |          |      |         |             |
| Corrective Action: | _____ |          |      |         | Date: _____ |

**Paint**

|                  |       |
|------------------|-------|
| Condition        | _____ |
| Other (Content)  | _____ |
| Other (Capacity) | _____ |

|                    |          |                     |                     |             |        |  |
|--------------------|----------|---------------------|---------------------|-------------|--------|--|
| Other (Type)       |          |                     |                     |             |        |  |
| <b>Berms</b>       |          |                     |                     |             |        |  |
| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |        |  |
| Metal              | Adequate | Walls Sufficent     | Base Sufficent      | Adequate    |        |  |
| Comment:           |          |                     |                     |             |        |  |
| Corrective Action: |          |                     |                     |             | Date:  |  |
| Contents           | #        | Capacity            | Type                | Tank ID     | SE GPS |  |
| METHANOL           | 1        | <50 BBLs            | STEEL AST           |             | ,      |  |
| Comment:           |          |                     |                     |             |        |  |
| Corrective Action: |          |                     |                     |             | Date:  |  |
| <b>Paint</b>       |          |                     |                     |             |        |  |
| Condition          |          |                     |                     |             |        |  |
| Other (Content)    |          |                     |                     |             |        |  |
| Other (Capacity)   |          |                     |                     |             |        |  |
| Other (Type)       |          |                     |                     |             |        |  |
| <b>Berms</b>       |          |                     |                     |             |        |  |
| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |        |  |
|                    |          |                     |                     |             |        |  |
| Comment:           |          |                     |                     |             |        |  |
| Corrective Action: |          |                     |                     |             | Date:  |  |
| Contents           | #        | Capacity            | Type                | Tank ID     | SE GPS |  |
| CONDENSATE         | 7        | 300 BBLs            | STEEL AST           |             | ,      |  |
| Comment:           |          |                     |                     |             |        |  |
| Corrective Action: |          |                     |                     |             | Date:  |  |
| <b>Paint</b>       |          |                     |                     |             |        |  |
| Condition          | Adequate |                     |                     |             |        |  |
| Other (Content)    |          |                     |                     |             |        |  |
| Other (Capacity)   |          |                     |                     |             |        |  |
| Other (Type)       |          |                     |                     |             |        |  |
| <b>Berms</b>       |          |                     |                     |             |        |  |
| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |        |  |
| Metal              | Adequate | Walls Sufficent     | Base Sufficent      | Adequate    |        |  |
| Comment:           |          |                     |                     |             |        |  |
| Corrective Action: |          |                     |                     |             | Date:  |  |
| <b>Venting:</b>    |          |                     |                     |             |        |  |
| Yes/No             | NO       |                     |                     |             |        |  |
| Comment:           |          |                     |                     |             |        |  |
| Corrective Action: |          |                     |                     |             | Date:  |  |
| <b>Flaring:</b>    |          |                     |                     |             |        |  |
| Type               |          |                     |                     |             |        |  |

|                    |       |  |
|--------------------|-------|--|
| Comment:           |       |  |
| Corrective Action: | Date: |  |

|  |
|--|
|  |
|--|

| Inspected Facilities  |               |       |      |             |           |         |    |               |    |
|-----------------------|---------------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID:          | 287345        | Type: | WELL | API Number: | 077-09167 | Status: | PR | Insp. Status: | PR |
| <b>Producing Well</b> |               |       |      |             |           |         |    |               |    |
| Comment:              | PR w/ Plunger |       |      |             |           |         |    |               |    |
| Corrective Action:    |               |       |      |             | Date:     |         |    |               |    |
| Facility ID:          | 287346        | Type: | WELL | API Number: | 077-09166 | Status: | PR | Insp. Status: | PR |
| <b>Producing Well</b> |               |       |      |             |           |         |    |               |    |
| Comment:              | PR w/ Plunger |       |      |             |           |         |    |               |    |
| Corrective Action:    |               |       |      |             | Date:     |         |    |               |    |
| Facility ID:          | 287347        | Type: | WELL | API Number: | 077-09165 | Status: | PR | Insp. Status: | PR |
| <b>Producing Well</b> |               |       |      |             |           |         |    |               |    |
| Comment:              | PR w/ Plunger |       |      |             |           |         |    |               |    |
| Corrective Action:    |               |       |      |             | Date:     |         |    |               |    |
| Facility ID:          | 287348        | Type: | WELL | API Number: | 077-09164 | Status: | PR | Insp. Status: | PR |
| <b>Producing Well</b> |               |       |      |             |           |         |    |               |    |
| Comment:              | PR w/ Plunger |       |      |             |           |         |    |               |    |
| Corrective Action:    |               |       |      |             | Date:     |         |    |               |    |
| Facility ID:          | 287349        | Type: | WELL | API Number: | 077-09163 | Status: | PR | Insp. Status: | PR |
| <b>Producing Well</b> |               |       |      |             |           |         |    |               |    |
| Comment:              | PR w/ Plunger |       |      |             |           |         |    |               |    |
| Corrective Action:    |               |       |      |             | Date:     |         |    |               |    |
| Facility ID:          | 287350        | Type: | WELL | API Number: | 077-09162 | Status: | PR | Insp. Status: | PR |
| <b>Producing Well</b> |               |       |      |             |           |         |    |               |    |
| Comment:              | PR w/ Plunger |       |      |             |           |         |    |               |    |
| Corrective Action:    |               |       |      |             | Date:     |         |    |               |    |
| Facility ID:          | 288356        | Type: | WELL | API Number: | 077-09214 | Status: | PR | Insp. Status: | PR |
| <b>Producing Well</b> |               |       |      |             |           |         |    |               |    |
| Comment:              | PR w/ Plunger |       |      |             |           |         |    |               |    |
| Corrective Action:    |               |       |      |             | Date:     |         |    |               |    |

**Reclamation - Storm Water - Pit**

**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Compaction       | Pass            | Compaction              | Pass                  |               |                          |         |
| Gravel           | Pass            | Gravel                  | Pass                  |               |                          |         |

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**COGCC Comments**

| Comment   | User     | Date       |
|---|----------|------------|
| <a href="#">Follow up inspection to verify equipment storage was temporary.</a> | conklinc | 03/15/2018 |

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description                    | URL   |
|--------------|--------------------------------|---|
| 689401041    | Wood Spangler 15-13 Pad Photos | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4404010">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4404010</a> |