

Inspection Photos

Location Name: Graefe #1, Croissant #1,#4 Tank Battery

Location ID: 317527 API: 05-123-06129

Inspection Date: 03/15/2018



Photo 1 – Tank Battery Sign



Photo 2 – Crude Oil ASTs looking northeast



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: Graefe #1, Croissant #1,#4 Tank Battery

Location ID: 317527 API: 05-123-06129

Inspection Date: 03/15/2018



Photo 3 – Crude oil AST loadout area



Photo 4 – Produced Water ASTs looking west



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: Graefe #1, Croissant #1,#4 Tank Battery

Location ID: 317527 API: 05-123-06129

Inspection Date: 03/15/2018



Photo 5 – North side of eastern crude oil AST. Oily material extends beneath tank.



Photo 6 – North side of center crude oil AST. Oily material extends beneath tank.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: Graefe #1, Croissant #1,#4 Tank Battery

Location ID: 317527 API: 05-123-06129

Inspection Date: 03/15/2018



Photo 7 – Location of former horizontal separator (foreground) and vertical heater treater (center-background). Looking northeast.



Photo 8 – Graefe #1 wellhead.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: Graefe #1, Croissant #1,#4 Tank Battery

Location ID: 317527 API: 05-123-06129

Inspection Date: 03/15/2018



Photo 9 – Demolished treater building, horizontal separator, and injection building moved to northeastern edge of location.



Photo 10 – Vertical heater treater stored north of location.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources