

Location Name: Croissant #4 Release API: 05-123-21651 Spill ID 454026 Inspection Date: 03/15/2018



Photo 1 – Photo of excavation near source area viewing north. Croissant #4 in background. Flowlines on left of photo (west end of excavation). A removed injection line serving the Croissant #1 was present east of the flowlines.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: Croissant #4 Release API: 05-123-21651 Spill ID 454026 Inspection Date: 03/15/2018



Photo 2 – Photo of excavation near source area viewing northeast. Croissant #4 in background/left.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources