

Augustus Energy Resources LLC, Cox 34-06
125-11762

Inspection #688301426

3/15/2018

Routine Inspection, TA/WO Status



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

AUGUSTUS ENERGY RESOURCES, LLC

COX 34-06

SENW 34 1S 44W

API # 05-125-11762

IN CASE OF EMERGENCY CALL: 970-332-3585 OR 911

03.15.2018



03.15

A photograph showing a dirt access road or path cutting through a field of tall, dry grass and some low-lying shrubs. The road is light brown and appears to be well-trodden. The surrounding vegetation is dense and somewhat overgrown. The text "Maintain access road." is overlaid on the image.

Maintain access road.

03.15.2018