

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/12/2018

Submitted Date:

03/12/2018

Document Number:

679904123**FIELD INSPECTION FORM**

Loc ID      Inspector Name:      On-Site Inspection ☐  
 321646      Welsh, Brian      2A Doc Num: \_\_\_\_\_

**Operator Information:**OGCC Operator Number: 17180Name of Operator: CITATION OIL & GAS CORPAddress: 14077 CUTTEN RDCity: HOUSTON      State: TX      Zip: 77269**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION  
☐ FOLLOW UP INSPECTION REQUIRED  
☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**17 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Rogers, Bob	719-767-8851	brogers@cogc.com	
Elsom, Lee Ann	281-891-1577	lelsom@cogc.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
207646	WELL	PR	01/01/1986	OW	017-06581	MPU 31-33	PR

**General Comment:**Routine Inspection

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:	Gravel road along edge of farm ground		
Corrective Action		Date:	

Overall Good: ☒

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	Lease sign by unit		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Stickers on tanks and treaters. Some stickers are faded and difficult to read. Install new NFPA labels		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Lease sign by oil tanks		
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:	Sticker on chemical drum		
Corrective Action:		Date:	

Emergency Contact Number:		
Comment:		
Corrective Action:		Date: _____

Overall Good: ☒

<b>Spills:</b>				
Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?

<b>Equipment:</b>			corrective date
Type: Compressor	# 1		
Comment:	Skid mounted electric booster compressor by wellhead		
Corrective Action:		Date:	
Type: Gas Meter Run	# 2		
Comment:	2-Meter runs on east side of treaters		
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:	American 456		
Corrective Action:		Date:	
Type: Ancillary equipment	# 4		

Comment:	Electric panel, cathodic rectifier, chemical drum w/containment, elec circ pump at oil tanks				
Corrective Action:				Date:	
Type: Horizontal Heater Treater	# 1				
Comment:	100bbl horizontal treater with metal shed				
Corrective Action:				Date:	
Type: Vertical Heater Treater	# 1				
Comment:	100bbl Vertical treater with metal shed				
Corrective Action:				Date:	
Type: Prime Mover	# 1				
Comment:	Electric motor				
Corrective Action:				Date:	
Type: LACT	# 0				
Comment:	Removed from location				
Corrective Action:				Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	400 BBLs	FIBERGLASS AST		38.880030,-102.780310
Comment:					
Corrective Action:					Date:

**Paint**

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:	Shared berms			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	400 BBLs	STEEL AST		38.880030,-102.780310
Comment:	Recycle tank				
Corrective Action:					Date:

**Paint**

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Inspector Name: Welsh, Brian

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment:					
Corrective Action:					Date:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	6	400 BBLS	STEEL AST		38.880060,-102.781310	
Comment:						
Corrective Action:						Date:

**Paint**

Condition					
Other (Content)					
Other (Capacity)					
Other (Type)					

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment:					
Corrective Action:					Date:

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:	Date:		

**Flaring:**

Type			
Comment:			
Corrective Action:	Date:		

Inspected Facilities									
Facility ID:	207646	Type:	WELL	API Number:	017-06581	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing. Central tank battery for (Section 33) 1200' ENE @ 38.880060/-102.781310								
Corrective Action:								Date:	

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass	Material Handling And Spill Prevention	Pass	

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401571197	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4399803">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4399803</a>