


## Inspection Photos

Location Name: Atlas Resources LLC, DBA Atlas Rockies LLC, Flatland 944-35-44

API: 05-095-06233



1. Lease sign



2. Meter shed with vertical gas separator



## Inspection Photos

Location Name: Atlas Resources LLC, DBA Atlas Rockies LLC, Flatland 944-35-44

API: 05-095-06233



3. Wellhead equipment



4. Prime mover have been removed.