

Inspection Photos

Location Name: Atlas Resources LLC, DBA Atlas Rockies LLC, Olt Jenbruns State 944-36-43

API: 05-095-06231



1. Lease sign



2. Meter shed

Inspection Photos

Location Name: Atlas Resources LLC, DBA Atlas Rockies LLC, Olt Jenbruns State 944-36-43

API: 05-095-06231



3. Wellhead equipment has been removed



4. Prime mover has been removed.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: Atlas Resources LLC, DBA Atlas Rockies LLC, Olt Jenbruns State 944-36-43

API: 05-095-06231



5. Backhoe tracks from removing prime mover



6. Backhoe tracks from removing prime mover



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources