

Inspection Photos

API# 071-06543

Operator: Timber Creek

Inspection Number: 680102753

Inspection Date: 3/7/2018





Photo#1:
Overview of Location to North.

March 7, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Timber Creek PA API#071-06543



Photo#2:
Well sign & staking that need to be removed.

March 7, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Timber Creek PA API#071-06543