

Inspection Photos

API# 071-06404

Operator: Timber Creek

Inspection Number: 680102754

Inspection Date: 3/7/2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:

Overview of Location to North. The entire location including the well pad, access road, is not recontoured, decompacted, or revegetated.

March 7, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Timber Creek PA API#071-06404



Photo#2:
Unutilized topsoil stockpile. Insert is of identifying topsoil sign.

March 7, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Timber Creek PA API#071-06404



Photo#3:

Silt fence at base of fill slope has become debris. Arrow indicates silt fence position.

March 7, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Timber Creek PA API#071-06404



Photo#4:
Erosion is occurring on Access Rd.

March 7, 2018




Photo#5:
Refer to Photo#4 description.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Timber Creek PA API#071-06404



Photo#6:
Erosion is occurring on Cut Slope

March 7, 2018



Photo#7:
Erosion is occurring on Fill Slope.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Timber Creek PA API#071-06404