

Inspection Photos

API#071-06183

Operator: Timber Creek

Inspection Number: 680102759

Inspection Date: 3/8/2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:

View over Location center to North.

March 8, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Timber Creek PA API#071-06183



Photo#2:
View over Location center to East.

March 8, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Timber Creek PA API#071-06183



Photo#3:
Diffuse knapweed is established on site.

March 8, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Timber Creek PA API#071-06183



Photo#4:
View of ground conditions on site.

March 8, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Timber Creek PA API#071-06183