

Inspection Photos
Location Name: Givan #1
API: 05-087-07712
Inspection Date: March 22, 2018



Photo #1 – View from southeast of stockpiled soil resulting from remediation efforts at historical release (Spill ID #454434).



Photo #2 – Exposed flowlines inside of historical release excavation.

Inspection Photos
Location Name: Givan #1
API: 05-087-07712
Inspection Date: March 22, 2018



Photo #3 – View from north of stockpiled soil encroaching into adjacent drainage. Note absence of stormwater BMPs.



Photo #4 – View from southern extent of soil stockpile, looking NW into adjacent drainage. Note absence of stormwater BMPs.

