




Cement Ticket

Rig # Third Party

| | |
|--|--------------------------------------|
| Customer Name Bill Barrett Corporation | Date Of Service: 3/14/2018 |
|--|--------------------------------------|

| | |
|------------------------------------|---------------------------|
| Location Scritsmier 1-26 | Equipment C1002 |
|------------------------------------|---------------------------|



Description Of Work **Start Time** 05:00 am **Stop Time** 11:00 am
 Drove to location signed JSA Spot in equipment (E/O 400' of 2 3/8 PH6 tubing surface 257' of 9 5/8 32.00#) have safety meeting with rig crew rigged up equipment pressure tested to 1000 psi established circulation with 2 bbls fresh water mixed and pumped (50 bbls 244 sx of CGNC at 15.8 verified by mud scale) to surface Rigged down valve and waited for rig crew to nipple down to top off washed equipment and moved from location

| Payroll Section | | | | | | |
|-----------------|------------------|-----------|----------|-------------|--------------|-------|
| | Employee | Emp # | Rev Hrs. | Travel Hrs. | Non Rev Hrs. | Total |
| Supervisor | Jaime, Gustavo | HGR010484 | 0.00 | 0.00 | 0.00 | 0.00 |
| Operator | Garcia, Roger | HGR010713 | 6.00 | 0.00 | 0.00 | 6.00 |
| Derrick | Cisneros, Hector | HGR010397 | 6.00 | 0.00 | 0.00 | 6.00 |
| FloorHand | Lopez, Alfonzo | HGR012245 | 6.00 | 0.00 | 0.00 | 6.00 |
| FloorHand | Campa, Nicolas | HGR010815 | 6.00 | 0.00 | 0.00 | 6.00 |
| FloorHand | Mendoza, Esteban | HGR010537 | 6.00 | 0.00 | 0.00 | 6.00 |

No Unreported Incidents Per
 My Signature _____

Ranger Tool Pusher _____

Customer/Agent: _____