

Well Name : McManus 33-22 2
API # : 067-08945



Photo 1: Wellhead sign.



Photo 2: Impacted gravel at wellhead.

Well Name : McManus 33-22 2
API # : 067-08945



Photo 3: Impacted gravel at muffler exhaust..



Photo 4: Wood debris pile on NE corner of location.