

# Inspection Photos

API: 05-067-06906

Operator: BP AMERICA PRODUCTION  
COMPANY

Inspection Date: 3/7/2018



**Photo 1. View of the project area from the southeastern corner facing center.**



**Photo 2. View of the western portion of the interim reclamation area from the northwestern corner facing westward. Revegetation is comprised of smooth brome (*Bromus inermis*), western wheatgrass (*Pascopyrum smithii*), and kochia (*Kochia scoparia*).**



**Photo 3. View of the eastern portion of the project area from the southeastern corner facing northward.**



**Photo 4. View of the northern portion of the project area. It is not apparent whether surface owner storage is part of the project disturbance.**