

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/26/2018

Submitted Date:

03/26/2018

Document Number:

679904177

**FIELD INSPECTION FORM**

Loc ID 303533 Inspector Name: Welsh, Brian On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10112  
Name of Operator: FOUNDATION ENERGY MANAGEMENT LLC  
Address: 5057 KELLER SPRINGS RD STE 650  
City: ADDISON State: TX Zip: 75001

**Findings:**

- 9 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
Grant, Rachael	918-585-1650 ext 212	regulatory@foundationenergy.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
253250	WELL	PR	06/01/2015	GW	125-07127	ALLEN 3-6	PR

**General Comment:**

[Routine Inspection](#)

Location			
<b>Lease Road:</b>			
Type	Access		
comment:	Gravel road through pasture		
Corrective Action:		Date:	
Overall Good: <input checked="" type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	OTHER		
Comment:	Lease sign for associated wells mounted to meter shed		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Lease sign mounted to fence		
Corrective Action:		Date:	
<b>Emergency Contact Number:</b>			
Comment:			
Corrective Action:			Date: _____
Overall Good: <input checked="" type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:	Metal panels around wellhead, VGS and meter shed		
Corrective Action:		Date:	
<b>Equipment:</b>			
Type: Gas Meter Run	# 5		corrective date
Comment:	Shared meter run for (Allen 3-6, 7-6, 11-6, 13-6, 15-6)		
Corrective Action:		Date:	
Type: Vertical Separator	# 5		
Comment:	5-Vertical gas separators 50% buried by meter shed		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Telemetry equipment		
Corrective Action:		Date:	
<b>Venting:</b>			
Yes/No	NO		
Comment:			

Corrective Action:		Date:	
--------------------	--	-------	--

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 253250 Type: WELL API Number: 125-07127 Status: PR Insp. Status: PR

**Producing Well**

Comment: [Producing. Casing production. Central meter run for \(ALLEN 3-6, 7-6, 11-6, 13-6, 15-6\) @ 39.82132/-102.23446](#)

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Gravel	Pass			
Other	Pass	Ditches	Pass			

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT