

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/20/2018

Submitted Date:

03/20/2018

Document Number:

679904148**FIELD INSPECTION FORM**

Loc ID _____ Inspector Name: _____ On-Site Inspection ☐
 321658 _____ Welsh, Brian _____ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 96730Name of Operator: WILLIFORD ENERGY COMPANYAddress: 6060 AMERICAN PLAZA SUITE 760City: TULSA State: OK Zip: 74135**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:9 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Hubbard, Corky	806-658-9758	whubbard@willifordenergy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
207697	WELL	SI	08/01/2016	OW	017-06632	RHOADES 5 7-32	SI

General Comment:[Routine Inspection](#)

Location

Lease Road:			
Type	Access		
comment:	Two track through pasture		
Corrective Action		Date:	

Overall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	Lease sign mounted to fence		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒

Spills:					
Type	Area	Volume			

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	Metal panels around wellhead		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Metal panels around cathodic rectifier		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:	National 228		
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	Ajax gas engine		
Corrective Action:		Date:	
Type: Ancillary equipment	# 3		
Comment:	Gas scrubber, day drum and cathodic rectifier		
Corrective Action:		Date:	

Inspected Facilities									
Facility ID:	207697	Type:	WELL	API Number:	017-06632	Status:	SI	Insp. Status:	SI
Producing Well									
Comment:	Well is SI at time of inspection. Central tank battery for (Rhoades 5-4, 5-32, 7-32, 6-32, 13-31 #2, 44-31 #5) 2000' NW @ 38.877860/-102.814420								
Corrective Action:								Date:	

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Compaction	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401581112	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4408991