

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/20/2018

Submitted Date:

03/20/2018

Document Number:

679904150**FIELD INSPECTION FORM**

Loc ID \_\_\_\_\_ Inspector Name: \_\_\_\_\_ On-Site Inspection ☐  
 321654 \_\_\_\_\_ Welsh, Brian \_\_\_\_\_ 2A Doc Num: \_\_\_\_\_

**Operator Information:**OGCC Operator Number: 96730Name of Operator: WILLIFORD ENERGY COMPANYAddress: 6060 AMERICAN PLAZA SUITE 760City: TULSA State: OK Zip: 74135**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION  
☐ FOLLOW UP INSPECTION REQUIRED  
☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**9 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Hubbard, Corky	806-658-9758	whubbard@willifordenergy.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
207690	WELL	PR	10/19/1986	OW	017-06625	RHOADES 5-32	PR

**General Comment:**[Routine Inspection](#)

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:	Dirt road through pasture		
Corrective Action		Date:	

Overall Good: ☒

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	Lease sign mounted to fence		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:			
Corrective Action:			
	Date:		

Overall Good: ☒

<b>Spills:</b>					
Type	Area	Volume			

In Containment: No

Comment:

☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:	Metal panels around wellhead		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Metal panels around cathodic rectifier		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Prime Mover	# 1		
Comment:	Ajax gas engine		
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:	Lufkin 320		
Corrective Action:		Date:	
Type: Ancillary equipment	# 3		
Comment:	Gas scrubber, day drum, cathodic rectifier		
Corrective Action:		Date:	



Inspected Facilities									
Facility ID:	207690	Type:	WELL	API Number:	017-06625	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing. Central tank battery for (Rhoades 5-4, 5-32, 7-32, 6-32, 13-31 #2, 44-31 #5) 3280' W @ 38.877860/-102.814420								
Corrective Action:								Date:	

--	--	--	--	--	--	--	--	--	--

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Compaction	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401581114	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4408993">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4408993</a>