

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/22/2018

Submitted Date:

03/22/2018

Document Number:

679904157**FIELD INSPECTION FORM**
 Loc ID 337528 Inspector Name: Welsh, Brian On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 10112Name of Operator: FOUNDATION ENERGY MANAGEMENT LLCAddress: 5057 KELLER SPRINGS RD STE 650City: ADDISON State: TX Zip: 75001**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:10 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Grant, Rachael	918-585-1650 ext 212	regulatory@foundationenergy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
286616	WELL	PR	06/01/2015	GW	125-10309	SHIVELY 41-1	PR

General Comment:

Routine Inspection

Location

Lease Road:			
Type	Access		
comment:	Trail through pasture		
Corrective Action	L	Date:	

Overall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	Lease sign by wellhead		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Lease sign for associated wells mounted to meter shed		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:			
Corrective Action:			
	Date:		

Overall Good: ☒

Spills:				
Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Fencing/:			
Type	SEPARATOR		
Comment:	Metal panels around VGS and meter shed		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Vertical Separator	# 3		
Comment:	3-Vertical gas separators 50% buried by meter shed		
Corrective Action:		Date:	
Type: Gas Meter Run	# 3		
Comment:	Shared meter run for (Shively 41-1, 31-1 & State 44-36)		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Telemetry equipment		
Corrective Action:		Date:	

Venting:			
Yes/No	NO		
Comment:			

Corrective Action:		Date:	
Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities									
Facility ID:	286616	Type:	WELL	API Number:	125-10309	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing. Casing production. Central meter run for (Shively 41-1, 31-1 & State 44-36)								
Corrective Action:								Date:	

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Other	Pass			

Comment: [Location and access are grassed over](#)

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401583912	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4411144