

Inspection Photos

Location Name: Ward Unit #44-3 Tank Battery

API: 05-121-10652

Inspection Date: March 22, 2018



Photo #1 – Battery sign.



Photo #2 – View of 500 bbl crude oil ASTs from SE corner.
Note shallow east berm.

Inspection Photos
Location Name: Ward Unit #44-3 Tank Battery
API: 05-121-10652
Inspection Date: March 22, 2018



Photo #3 – Localized accumulations of oily waste and damaged berms on north side of crude oil ASTs.



Photo #4 – Historical accumulation of oily waste and erosion of base of earthen berm on west side of crude oil ASTs.

Inspection Photos

Location Name: Ward Unit #44-3 Tank Battery

API: 05-121-10652

Inspection Date: March 22, 2018



Photo #5 – Stockpile of oily waste resulting from Spill ID #454249 remaining at entrance to facility.



Photo #6 – 500 bbl produced water AST located on north side of tank battery (view from west). Note shallow earthen berms.



Inspection Photos

Location Name: Ward Unit #44-3 Tank Battery

API: 05-121-10652

Inspection Date: March 22, 2018



Photo #7 – View of skim tank on north side of tank battery. Note shallow earthen berms and absence of required NFPA placard as well as volume/content labels.



Photo #8 – Unused equipment (junk pipe) located on east side of 500 bbl produced water AST.



Inspection Photos

Location Name: Ward Unit #44-3 Tank Battery

API: 05-121-10652

Inspection Date: March 22, 2018



Photo #9 – View of shallow earthen berm shared by 200 bbl and 400 bbl produced water ASTs on east side of tank battery.



Photo #10 – Junk pipe located at NW corner of east pit. Note that pit lacks required 2' of freeboard and method of monitoring/maintaining freeboard required by Rule 902.b.



Inspection Photos

Location Name: Ward Unit #44-3 Tank Battery

API: 05-121-10652

Inspection Date: March 22, 2018



**Photo #11 – Open excavation related to Pit ID #104604.
Work is underway to close pit under Remediation Project
#10429.**



**Photo #12 – Additional excavation at NE corner of Pit ID
#104604.**



Inspection Photos

Location Name: Ward Unit #44-3 Tank Battery

API: 05-121-10652

Inspection Date: March 22, 2018



Photo #13 – West produced water pit (Pit ID #117678) with mesh-covered tinhorn at SE corner.



Photo #14 – West produced water pit has adequate freeboard.

