

Inspection Photos
Location Name: Green #1-1
Location ID: 310566



Photo 1: Location, looking SW



Photo 2: Wellhead

Inspection Photos
Location Name: Green #1-1
Location ID: 310566



Photo from prior inspection for comparison



Photo 3: Pump jack removed

Inspection Photos
Location Name: Green #1-1
Location ID: 310566



Photo from prior inspection for comparison



Photo 4: Stained soil has been treated

Inspection Photos
Location Name: Green #1-1
Location ID: 310566



Photo from prior inspection for comparison



Photo 5: Decal is for incorrect operator, with incorrect emergency number

Inspection Photos
Location Name: Green #1-1
Location ID: 310566




Photo from prior inspection for comparison



Photo 6: Decal for incorrect operator obscured.



Inspection Photos
Location Name: Green #1-1
Location ID: 310566



Photo from prior inspection for comparison



Photo 7: Stained soil at truck loadout.

Inspection Photos
Location Name: Green #1-1
Location ID: 310566



Photo 8: Unused riser at SE corner of produced water pit



Photo 9: Unused risers at SE corner of tank battery