



Silt fence installed on March 27



Large overburden pile



Silt fence detail



Removal of overburden pile from drainage



Reconstruction of drainage wall



Reconstructed drainage wall looking south down drainage



Reconstructed east drainage wall



Wall and silt fence



Creating flat surface on top of dike



Installation of erosion control blankets



Installation of erosion control blankets



Reconstructed drainage wall looking northwest