

Inspection Photos
Location Name: KILDARE #42-20
Facility ID # 263971



Photo 1. Location sign



Photo 2. Wellhead

Inspection Photos
Location Name: KIDARE #42-20
Facility ID # 263971



Photo 3. Stained soil around prime mover



Photo 4. Unused equipment stored on location