

Final Reclamation Inspection

March 30, 2018

Operator: HRBEK* RANDALL L - 41365

API: 05-123-07046

Inspection Document #: 682403427

Weld County, CO

SWNW Section 3 T11N R57W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: LONG #1
API: 05-123-07046



Google Earth aerial imagery taken October 15, 2015 appears to indicate surface disturbance from a pit, approximately 375 feet southeast of the well location (Lat/Long in above image).




Photo 1. Photo taken from the approximate pit, facing North. Appears the pit has been backfilled but vegetation is not reflective of reference area vegetative levels. The vegetative growth in the central area of the pit consists of Cheatgrass (*Bromus tectorum*). Other areas of the pit are not reflective of reference area vegetative levels.



Photo 2. Reference photo taken west of the pit, facing West. Reference area vegetative growth consists of, but not limited to, Blue grama (*Bouteloua gracilis*).



Photo 3. Photo taken from the approximate well location, facing North. Well location appears reflective of reference area vegetative levels.



Photo 4. Photo taken from the approximate well location, facing East. Well location appears reflective of reference area vegetative levels.