

Inspection Photos
Location Name: Hotchkiss 12-90 #1-34
API: 05-051-06074



Leaking hammer union on production T.



Puddle to the north of the well head.

Inspection Photos
Location Name: Hotchkiss 12-90 #1-34
API: 05-051-06074



Release point.



Gunnison Energy representative isolating release point.