

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/28/2018

Submitted Date:

04/02/2018

Document Number:

685304566**FIELD INSPECTION FORM**Loc ID 326067 Inspector Name: St John, William (Cal) On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10000Name of Operator: BP AMERICA PRODUCTION COMPANYAddress: 380 AIRPORT RDCity: DURANGO State: CO Zip: 81303**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**4 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Beebe, Sabre	970-779-9398	Sabre.Beebe@bp.com	SW Inspection Reports
Inspections, All		SanJuanCOGCC@bp.com	SW Inspection Reports

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
215812	WELL	PR	03/16/1990	GW	067-07417	MW JOHNSON A 1	PR

General Comment:[Inspection conducted in response to noise complaints 200445648.](#)[A-scale sound survey conducted for noise from pumping unit was accomplished 3/26/2018 document number 685200425. Corrective actions resulting from this inspection contained in equipment and stormwater sections are still applicable.](#)[C-scale survey attempt at residence to investigate complainant's description engine noise problem were not accomplished due to wind speeds in excess of 5 mph. Wind speeds were 10 - 12 mph with gust over 20 mph.](#)

Inspected Facilities									
Facility ID:	215812	Type:	WELL	API Number:	067-07417	Status:	PR	Insp. Status:	PR
Complaint									
Comment:	See complaint number 200445648.								
Corrective Action:				Date:					