

Inspection Photos
Location Name: Weld #5-28
Location ID: 306282



Photo 1: Location, looking NE



Photo 2: Wellhead, looking SE. Well is TA.

Inspection Photos
Location Name: Weld #5-28
Location ID: 306282



Photo 3: Stained soil at wellhead



Photo 4: Stained soil in treater house.